Location: Sulphur Mines Dome Date: Monday, July 15, 2024 Inspector Name(s): Billy Carnes	Time of Arrival:		INJI I	ECTION & MI 617 NORTH BATON ROUC	NSERVATION NING DIVISIO 3RD STREET 5E, LA 70802					En en el constante de la constante
Other personnel on site: Patrick Tucker [Westlake] Capt. Richard [Stan's Airboats] Vance Hill [Yellowrock]										
Weather Conditions (Temp/Wind Speed/Direction, etc.): 82* to 90* Partly Cloudy W 3 mph										
Any planned work for today: Check bubbling site's, some Westlake Cavern well pressures, check some of Yellowrock well pressures										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL-bubbling site's	Cavern Well 2	Cavern Well 2a	Carvern Well 4	Cavern Well 20	Yellowrock Wells
Pelican Land Surveyors are surveying today for Well locations & crosssections of Well locations		Pad dry @ time of inspection, not able to observe bubbling @ time of inspection		Still bubbling	CL-3,4,5,6,18 & 24 were active @ time of inspection all other bubbling site's were inactive					#1017 320 psi tubing 320 psi casing # 1012 60 psi tubing 60 psi casing S-7 50 psi tubing 0 psi casing S-4 5 psi tubing 180 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)	643 psi		124 psi			261 psi	1.99 psi	258 psi	875 psi	
Casing Pressure (if applicable)			429 psi			736 psi		292 psi		
Bubbling?				yes	yes					
Sheen?				yes	no					
Oil?				yes	no					
Odor?				yes	no					
Any new remedial work?				no	no					
Any impact to vegetation?				no	no					
Any impact to wildlife?				no	no					