INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, July 22, 2024 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM Inspector Name(s): Billy Carnes Other personnel on site: Alex Hardman [Westlake] Capt. Richard [Stan's Airboats] Vance Hill [Yellowrock] Weather Conditions (Temp/Wind Speed/Direction, etc.): 84* to 85* Partly Cloudy SSW 7 mph Any planned work for today: Check bubbling site's, some Cavern Well pressures & some Yellowrock Well pressures										<ul> <li>Image: A state of the state of</li></ul>
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	<b>CL-1</b> (near BW-22, west side of Central Lake)	CL bubbling site's	Cavern Well 2	Cavern Well 2a	Cavern Well 20		Yellowrock
Pelican Land Surveyors are TOPO'ing the proposed levee route & the Well locations		Fluid on pad today observed bubbling	Downhole pressure gauge 1390 psi injecting 543 gpm		CL- 3,4,5,6,21,23,,24 observed bubbling @ time of inspection, all others were inactive					# 1017 320 psi tubing 320 psi casing # 1012 60 psi tubing 60 psi casing S-7 50 psi tubing 0 psi casing S- 4 5 psi tubing 180 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)	642 psi		128 psi			202 psi	1.78 psi			
Casing Pressure (if applicable)			430 psi			531 psi		882 psi		
Bubbling?		yes		yes	yes					
Sheen?		no		yes	no					
Oil? Odor?		no		yes	no no					
Any new remedial work?		no		no no	no					
Any impact to vegetation?		no		no	no					
Any impact to wildlife?		no		no	no					