INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, July 29, 2024 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM Inspector Name(s): Billy Carnes Other personnel on site: Josh Bradley [Westlake] Vance Hill [Yellowrock] Capt. Richard [Stain's Airboat's] R & R Construction doing levee work Weather Conditions (Temp/Wind Speed/Direction, etc.): 82* to 90* partly cloudy SSW 7 mph Any planned work for today: Check bubbling site's, some Cavern Well pressures & some Yellowrock well pressures										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL bubbling site's	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
R & R Construction is doing clearing work for the Levee around possible Sinkhole inpack area.		Fluid on pad today	Injecting 544 gpm bottom hole pressure gauge reading 1417 psi	still bubbling w/oil sheen	CL-3,4,5,17,21 & 24 were active @ time of inspection all other bubbling site's were inactive @ time of inspection					#1017 310 psi tubing 320 psi casing #1012 50 psi tubing 50 psi casing S-7 50 psi tubing Opsi casing S-4 5 psi tubing 135 psi casing.
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			110 psi			155 psi	1.68 psi	134 psi		
Casing Pressure (if applicable)	641 psi		430 psi			678 psi		735 psi	886 psi	
Bubbling?		yes		yes	yes					
Sheen?		no		yes	no					
Oil?		no		yes	no					
Odor?		no		yes	no				+	
Any new remedial work?		no		no	no					
Any impact to vegetation? Any impact to wildlife?		no		no no	no					
		•	•			•			•	