INSPECTION FORM         OFFICE OF CONSERVATION         INJECTION & MINING DIVISION         INJECTION & MINING DIVISION         617 NORTH 3RD STREET         BATON ROUGE, LA 70802    Location: Sulphur Mines Dome Date: Monday, August 5, 2024 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM Inspector Name(s): Billy Carnes Other personnel on site: Josh Bradley [Westlake] Capt. Gavin [Westlake] Vance Hill [Yellowrock] R & R Construction         Weather Conditions (Temp/Wind Speed/Direction, etc.): 86* to 92* sunny NE 3 mph Any planned work for today: Check Cavern Well pressures, Yellowrock Well Pressures & bubbling site's											
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	<b>CL-1</b> (near BW-22, west side of Central Lake)	CL-bubbling site's	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock	
R & R construction is working on clearing for levee ROW		Pad dry - no bubbling observed	1416 psi downhole gauge injecting 546 gpm	Same as the past several inspections	bubbling site's 3,4,5,6,21 & 24 bubbling @ time of inspection all other site's were inactive @ time of inspection			Operator is bleeding pressure off the Well for future workover		# 1013 Rig on Well #1017 300 psi tubing # 1012 50psi tubing 50 psi casing S-7 50 psi tubing S-4 5 psi tubing 135 psi on	
Photos taken? (save to F: drive)											
Tubing Pressure (if applicable)			111 psi			120 psi	1.76				
Casing Pressure (if applicable)	642 psi		430 psi	ļ		508 psi			893 psi		
Bubbling?				yes	yes						
Sheen?				yes	no						
Oil?				yes	no						
Odor?				yes	no						
Any new remedial work?				no	no						
Any impact to vegetation?				no	no						
Any impact to wildlife?				no	no						