INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, August 12, 2024 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM Inspector Name(s): Billy Carnes Other personnel on site: Randy Broussard [Westlake] Vance Hill [Yellowrock] Capt. Stan [Stan's Airboats] R & R Construction Weather Conditions (Temp/Wind Speed/Direction, etc.): 79* to 93* partly cloudy SSE 1 mph Any planned work for today: Check Some Cavern Well pressures, Check some Yellowrock Well pressures & check bubbling site's										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL- bubbling site	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
R & R Construction clearing the Vegetation behind & on the east side of Cavern 7b Well pad. Rig on Westlake Cavern Well #4 Yellowrock has a Workover Rig on well #1031		Pad dry-no bubbling oberved	1414 psi BHG injecting 540 gpm	Observed that bubbling site hasn't change for the last several inspections	were inactived @			Well is off line due to Well Workover		workover #1017 300 psi tubing 300 psi Casing #1012 60 psi tubing 60 psi casing S-7 50 psi tubing 0 psi casing S-4 5 psi tubing 130 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			107 psi			317 psi	1.84 psi			
Casing Pressure (if applicable)	641 psi		426 psi			771 psi			898 psi	
Bubbling?				yes	yes					
Sheen?				yes	no					
Oil?				yes	no					ļ
Odor?				yes	no					ļ
Any new remedial work?				no	no					
Any impact to vegetation?				no	no					
Any impact to wildlife?				no	no					