INSPECTION FORM   OFFICE OF CONSERVATION   INJECTION & MINING DIVISION   INJECTION & MINING DIVISION   INJECTION & MINING DIVISION   617 NORTH 3RD STREET   BATON ROUGE, LA 70802   Location: Sulphur Mines Dome Date: Monday, August 19, 2024 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM Inspector Name(s): Billy Carnes Other personnel on site: Josh Bradley [Westlake] Vance Hill [Yellowrock] Capt. Kade [Stan's aiboat's] Meather Conditions (Temp/Wind Speed/Direction, etc.): 79 * to 90 * Partly Cloudy NNW 8 Any planned work for today: Check subbling site's, check some Cavern Well Pressures & check well pressures										
Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west	CL-bubbling site's	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
(location description):				side of Central Lake)						(all brine and oil flowlines)
R & R Construction working on levee and other site work. Pelican Land Surveying working on levee TOPO. Longquest still has a Workover Rig on Cavern Well # 4		Pad dry no bubbling observed	Operator injecting 456 gpm also down hole pressure 1416 psi	Still have bubbling with a oil sheen	CL-3,4,5,6,21 & 24 still bubbling, all other bubbling site's were inactive @ time of inspection			Rig on Well		#1017 310 psi tubing 310 psi casing #1012 80 psi tubing 80 psi casing S-7 60 psi tubing 0 psi casing S-4 5 psi tubing 130 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			95 psi			123 psi	1.64 psi			
Casing Pressure (if applicable)	641 psi		430 psi			574 psi			902 psi	
Bubbling?				yes	yes					
Sheen?				yes	no					
Oil?				yes	no					
Odor?				yes	no					
Any new remedial work?				no	no					ļ
Any impact to vegetation?				no	no					ļ
Any impact to wildlife?				no	no					
L										