INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, August 26, 2024 Time of Arrival: 9:00 AM Time of Departure: 1:00 P Inspector Name(s): Billy Carnes Other personnel on site: Kevin Levergne [Westlake] Vance Hill [Yellowrock] Kade Mott [Stan's airboats] Weather Conditions (Temp/Wind Speed/Direction, etc.): 84* to 90* partly cloudy E 7 mph Any planned work for today: Check bubbling site's, Check some Yellowrock & Westlake Well prssure's										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	<b>CL-1</b> (near BW-22, west side of Central Lake)	CL- bubbling site's	s Cavern Well 4	Cavern Well 2	Cavern Well 2a	Cavern Well 20	Yellowrock
Recon & contractors are do site surveying for the drilling of the observation Wells. R & R construction working on containment levee		Pad dry - no bubbling observed	1415 dhp 481 gpm injection	Sill bubbling with oil sheen	CL - 3,4,5,21 & 34 were active @ time of inspection, all other CL bubbling site's were inactive @ time of inspection					#1017 310 psi tubing 310 psi casing #1012 80 psi tubing 80 psi Casing S-7 60 psi tubing 0 psi on the casing S- 4 5 psi tubing 130 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			97 psi					2.15 psi		
Casing Pressure (if applicable)	641 psi		428 psi				735 psi	ļ	908 psi	ļ
Bubbling?				yes	yes					
Sheen?				yes	no					
Oil?				yes	no					
Odor?				yes	no					
Any new remedial work?				no	no					
Any impact to vegetation?				no	no					
Any impact to wildlife?				no	no					