Location: Sulphur Mines Dome Date: 09-04-2024. Inspector Name(s): Billy Carnes Other personnel on site: Kevin Leve	Time of Arrival: ergne [Westlake] Van		INJE 0 AM	ECTION & MI 617 NORTH BATON ROUG	NSERVATION NING DIVISIO 3RD STREET 5E, LA 70802					E CONTRACTOR O C
Weather Conditions (Temp/Wind Speed/Direction, etc.): 82* to 89* Cloudy ENE 11 mph										
Any planned work for today: Check bubbling site's, Check some Cavern Well pressures & check some of Yellowrock Well pressures										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL-bubbling site's	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock Wells
R & R Construction doing clearing work/levee prep work. Recon is surveys the soil under where the levee is going to be installed										#1017 300 psi tubing 300 psi casing #1012 120 psi
		Slight bubbling on pad, fluid on pad today	504 gpm injection 1416 psi downhole pressure gauge	Still bubbling with slight oil sheen	3,4,5,21 & 24 still bubbling all other CL bubbling sites were inactive @ time of inspection			Cavern is being MIPT @ time of inspection		tubing 120 psi casing S-7 60 psi tubing 0 psi casing S-4 10 psi tubing 130 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			99 psi				2.30 psi			
Casing Pressure (if applicable)	642 psi		428 psi			762 psi			908 psi	
Bubbling?		yes		yes	yes					
Sheen?		no		yes	no					
Oil?		no		yes	no					
Odor?		no		yes	no					
Any new remedial work?		no		no	no					
Any impact to vegetation?		no		no	no					
Any impact to wildlife?		no		no	no					