INSPECTION FORM OFFICE OF CONSERVATION INSECTION & MINING DIVISION INSECTION & MINING DIVISION INSECTION & MINING DIVISION INSECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Location: Sulphur Mines Dome Date: Monday, September 9, 2024 Ime of Arrival: 9:00 AM Ime of Departure: 1:00 PM Impersonnel on site: Kevin Levergne [Westlake] Vance Hill [Yellowrock] Collin Todd [Stains Airboats] Meather Conditions (Temp/Wind Speed/Direction, etc.): 73* to 83* Sunny NE 11 mph Any planned work for today: Check subbling site's, Check some Cavern Well pressures & check well pressures										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL Bubbling site's	Cavern Well 2	Cavern Well 2a (Central Lake bubbling site)	Caven Well 4	Cavern Well 20	Yellowrock
Operator's on the Dome are preparing for the Storm in the Gulf, no extra work on levee or Well pads		Fluid on pad bubbling observed	498 gpm injection 1416 psi Downhole gauge	Still bubbling with small oil sheen	CL-3,4,5 & 24 were active @ time of inspection, all other bubbling site's were inactived					#1017 300 psi tubing 300 psi tubing// #1012 180 psi tubing 180 psi casing// S-7 60 psi tubing 0 psi casing// S-4 10 psi tubing 110 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			98 psi				2.11 psi			
Casing Pressure (if applicable)	642 psi		428 psi			775 psi		292 psi	921 psi	
Bubbling?		yes		yes	yes					
Sheen?		no		yes	no					
Oil?		no		yes	no					
Odor? Any new remedial work?		no		yes no	no					
Any impact to vegetation?		no		no	no					
Any impact to wildlife?		no		no	no					