

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Wednesday, September 18, 2024 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: Randy Broussard [Westlake] Vance Hill [Yellowrock] Kade Matt [Stain's Airboats]

Weather Conditions (Temp/Wind Speed/Direction, etc.): Sunny 78* to 88* W 2 mph

Any planned work for today: Check bubbling site's, some Cavern Well pressures & some of the Yellowrock Well pressures



Inspection locations: Sulphur Mines Salt Dome	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL bubbling site's	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock Wells
R & R construction is working on containment levee		Pad dry - no	injecting 545 gpm 1414 psi on the downhole gauge	still bubbling w/oil sheen	CL-3,4,5,6,21 & 24 still bubbling all others were inactived @ time of inspection					#1017 300 psi tubing 300 psi casing// #1012 50 psi tubing 50 psi casing// S-7 60 psi tubing 0 psi casing// S-4 10 psi tubing 110 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			100 psi				1.99 psi			
Casing Pressure (if applicable)	643 psi		427 psi			761 psi		277 psi	927 psi	
Bubbling?				yes	yes					
Sheen?				yes	no					
Oil?				yes	no					
Odor?				yes	no					
Any new remedial work?				no	no					
Any impact to vegetation?				no	no					
Any impact to wildlife?				no	no					