Location: Sulphur Mines Dome Date: Monday, September 23, 2024 Inspector Name(s): Billy Carnes Other personnel on site: DeAnn Ch	Time of Arrival:		INJE E	CTION & MI 617 NORTH BATON ROUC	NSERVATION NING DIVISIO 3RD STREET 5E, LA 70802	ON				
Other personnel on site: DeAnn Chapman [Westlake] Vance Hill [Yellowrock] Kade Matt [Stain's Airboats]   Weather Conditions (Temp/Wind Speed/Direction, etc.): Sunny 81* to 89* SSE 2mph										
Any planned work for today: Check bubbling site's, some Cavern well pressures & some of Yellowrock Well pressures										
Inspection locations: Sulphur Mines Salt Dome	Cavern 6X	Cavern Well 7A	Cavern Well 7B	<b>CL-1</b> (near BW-22, west side of Central Lake)	CL-Bubbling site's	Cavern Well 2	Cavern Well 2a	Cavern Well 4 (Central Lake bubbling site)	Cavern Well 20	Yellowrock
R & R construction working on levee ERM getting air samples Recon working on the levee		Pad dry - no bubbling observed	Injecting 578 gpm 1414 psi on the downhole pressure gauge	Still bubbling with oil sheen	3,4,5,21 & 24 still bubbling all otherCL bubbling site's were inactive @ time of inspection					#1017 300 psi tubing 300 psi casing//#1012 50 psi tubing 50 psi tubing 0 psi casing//S-4 10 psi tubing 110 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			101 psi				1.72 psi			
Casing Pressure (if applicable)	644 psi		427 psi			763 psi		285 psi	930 psi	
Bubbling?				yes	yes					
Sheen?				yes	no					
Oil?				yes	no					
Odor?				yes	no					
Any new remedial work?				no	no					
Any impact to vegetation?				no	no					
Any impact to wildlife?				no	no					