Location: Sulphur Mines Dome Date: Inspector Name(s): Billy Carnes Other personnel on site: Kevin Law	J DN 0 PM									
Weather Conditions (Temp/Wind Speed/Di Any planned work for today: Check but		76* to 88* Sunny SE ome of Cavern Well p		me of the Yellowrock	well pressures			A A	BW. No. 4 Isadire SN 2023	
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL-3,4,5,18,21,24 Bubbling Site's	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
R & R Construction is working on the Levee		Pad dry no bubbling observated	517 gpm injection 1416 psi on the down hole gauge		still bubblings all other bubbling site's were inactive @ time of inspection					#1017 300 psi tubing 300 psi casing// #1012 50 psi tubing 50 psi casing// S-7 60 psi tubing 0 psi casing// S-4 10 psi tubing 100 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			103 psi				1.60 psi			
Casing Pressure (if applicable)	284 psi		413 psi			284 psi		297 psi	927 psi	
Bubbling?				yes	yes					
Sheen?				yes	no					
Oil?				yes	no					
Odor?				yes	no					
Any new remedial work?				no	no					
Any impact to vegetation?				no	no					
Any impact to wildlife?				no	no					
										<u> </u>
1	1	1		1	1					1