INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, October 7, 2024 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM Inspector Name(s): Billy Carnes Other personnel on site: Randy Broussard [Westlake] Vance Hill [Yellowrock] Kade Mott [Stan's Airboats] Weather Conditions (Temp/Wind Speed/Direction, etc.): 74* to 88 * Sunny NE 9 mph										
Any planned work for today: Check bubbling site's, Cavern Well pressure's and some of Yellowrock Well pressure's										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A		<b>CL-1</b> (near BW-22, west side of Central Lake)	CL-3,4,5,6,23 & 24	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
R & R Construction still working on levee		Pad dry no bubbling	•	Still bubbling with oil sheen	Still active all others were inactive today					#1017 300psi tubing 300 psi casing//#1012 50 psi tubing 50 psi casing//S-7 60 psi tubing 0 psi casing//S-4 10 psi tubing 100psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)	642 psi		92 psi			277 psi	1.29 psi	269 psi	924 psi	
Casing Pressure (if applicable)			429 psi							
Bubbling?				yes	yes					
Sheen?				yes	no					
Oil?				yes	no					
Odor?				yes	no					
Any new remedial work?				no	no					
Any impact to vegetation?				no	no					
Any impact to wildlife?				no	no					