INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION INJECTION & MINING DIVISION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Location: Sulphur Mines Dome Inspector Name(s): Billy Carnes Cather personnel on site: Mosh Brradley [Westlake] Vance Hill [Yellowrock] R.Zaunbrech [Stan's Airboats] Mether Conditions (Temp/Wind Speed/Direction, etc.): 73* to 86* Sunny WSW 5 mpl Any planned work for today: Check bubbling site's, some Cavern well pressures & some of Yellowrock Well pressures										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL bubbling site's	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
R & R construction working on levee. Lonquist & Rid crew working on Cavern Wel 7b		Pad dry no bubbling	1415 psi downhole pressure gauge Injecting 583 gpm	Still bubbling with oil sheen	CL sites bubbling today that I observed 3,4,5,6,18,21 & 24 all other bubbling site's were inactive @ time of inspection					#1017 100 psi tubing 100 psi casing// #1012 50 psi tubing 50 psi casing// S-7 55 psi tubing 0 psi casing// S-4 10 psi tubing 150 psi casing
Tubing Pressure (if applicable)			105 psi				1.02 psi			
Casing Pressure (if applicable)	641 psi		429 psi			275 psi		276 psi	919 psi	
Bubbling?				yes	yes					
Sheen? Oil?				yes yes	no					
Oll? Odor?				yes	no					
Any new remedial work?				no	no					
Any impact to vegetation?				no	no		1			
Any impact to wildlife?				no	no					