INSPECTION FORM OFFICE OF CONSERVATION INSECTION & MINING DIVISION INJECTION & MINING DIVISION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Ider monday, October 21, 2024 me of Arrival: 9:00 AM me of Departure: 1:00 pm Inspector Name(s): Billy Carnes Cher personnel on site: Josh Bradley [Westlake] Vance Hill [Yellowrock] Collin Todd [Star's Airboats] Mether Conditions (Temp/Wind Speed/Direction, etc.): 57* to 80* Sunny ENE 4 mpl Any planned work for today: Check bubbling site's some Cavern well pressures & some Yellowrock well pressures										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL bubbling sites [Central Lake Bubbling site]	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
R & R working on levee. Phoenix is clearing brush for well pads		Pad dry no bubbling observed	1415 psi DHG injecting 541 gpm	Still bubbling with oil sheen	l observed 3,4,5,6,22 & 24 were still bubbling & all others were inactive @ time of inspection					#1017 100 psi tubing 100 psi casing// #1012 50 psi tubing 50 psi casing// S-7 60 psi tubing 0psi casing// S-4 12 psi tubing 95 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			110 psi				1.33 psi			
Casing Pressure (if applicable)	640 psi		430 psi			280 psi		280 psi	912 psi	
Bubbling?				yes						
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						