

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, October 28, 2024 Time of Arrival: 9:00 AM Time of Departure: 12:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: Josh bradley [Westlake] Vance Hill [yellowrock] Richard Timpa {Stain's Airboats]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 69* to 82* Sunny SE 4 mph

Any planned work for today: Check bubbling sites, some cavern Well pressures & some of Yellowrock Well pressure's



Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL-bubbling site's	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
(location description):				(near BW-22, west						
				side of Central						
				Lake)						1
R & R construction doing levee work										
ERM doing sampling work										
										#1017 140 psi
					CL-3,4,5,6,22,23 &					tubing 140 psi
					24 were active					casing// #1012 40
					bubbling at time of					psi tubing 40 psi
					inspection all other					casing// S-7 60 psi
		Pad dry no bubbling	E26 ann injection	still bubbling with	bubbling sites were inactive at time of					tubing 60 psi casing//S-4 12 psi
		observed	1413 psi DHG	oil sheen	inspection					tubing 95 psi casing
Photos taken? (save to F: drive)		Observed	1413 psi biro	on sheen	Inspection					tubing 33 par cuanti
·										
Tubing Pressure (if applicable)			107 psi				1.45 psi			
Casing Pressure (if applicable)	640 psi		425 psi			273 psi		271 psi	910 psi	
Bubbling?				yes						
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						