INSPECTION FORM   OFFICE OF CONSERVATION   INJECTION & MINING DIVISION   INJECTION & MINING DIVISION   INJECTION & MINING DIVISION   ATT NORTH 3RD STREET   Batton ROUGE, LA 70802   Location: Sulphur Mines Dome Inter Monday, November 4, 2024 Inter of Arrival: 9:00 AM Inter of Departure: 1:00 PM Inter personnel on site: DeAnn Chapman [Westlake] Vance Hil [Yellowrock] Wether Conditions (Temp/Wind Speed/Direction, etc.): 80* to 88* Sunny E1 2 mph Any planned work for today: Lock @ bubbling site's and check some cavern Well pressures along with some Yellowrock well pressures'										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	<b>CL-1</b> (near BW-22, west side of Central Lake)	CL bubbling site's	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
R & R Construction workingon levee Recon is also doing work on the levee.		Pad dry no bubbling seen or observed	534 gpm injecting 1415 psi DHG	still bubbling with oil sheen	No bubbling site's in Central Lake were inspected because of Airboat not on site today					#1017 260 psi on tubing 260 psi casing// #1012 40 psi tubing 40 psi casing// S-7 60 psi tubing 60 psi casing// S-4 12 psi tubing 95 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			165 psi				1.45 psi			
Casing Pressure (if applicable)	640 psi		109 psi			280 psi		278 psi	910 psi	
Bubbling?				yes						
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation? Any impact to wildlife?				no no						