| INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Tuesday, November 12, 2024 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM Inspector Name(s): Billy Carnes Other personnel on site: Randy Broussard [Westlake] Vance Hill [Yellowrock] Richard Timpa [Stain's Airboats] Weather Conditions (Temp/Wind Speed/Direction, etc.): 63* to 78* Sunny NE 7 mph Any planned work for today: Check bubbling site's, Some Cavern Wells and some Yellowrock production Wells | | | | | | | | | | | |
|--|-----------|---|---|--|--|---------------|----------------|---------------|----------------|---|--|
| Inspection locations: (location description): | Cavern 6X | Cavern Well 7A | Cavern Well 7B | CL-1 (near BW-22, west side of Central Lake) | CL bubbling site's | Cavern Well 2 | Cavern Well 2a | Cavern Well 4 | Cavern Well 20 | Yellowrock Wells | |
| Blood hound is working on levee | | Fluid on pad today bubbling observed | Injecting 500 gpm Bottom hole pressure 1412 psi | Still bubbling w/oil sheen | CL- 3,4,5,6,18,21 & 24 site's still bubbling all others were inactive today @ time of inspection. | | | | | #1017 150 psi tubing 150 psi casing// #1012 50 psi tubing 50 psi casing// S-7 60 psi tubing 0 psi casing// S-4 12 psi tubing 95 psi casing | |
| Photos taken? (save to F: drive) | | | | | | | | | | | |
| Tubing Pressure (if applicable) | | | 102 psi | | | | 1.33 psi | | | | |
| Casing Pressure (if applicable) | 640 psi | | 253 psi | | | 276 psi | | 277 psi | 908 psi | | |
| Bubbling? | | yes | | Yes | yes | | | | | | |
| Sheen? | | no | | Yes | no | | | | | | |
| Oil? | | no | | Yes | no | | | | | | |
| Odor? | | no | | Yes | no | | | | | | |
| Any new remedial work? | | no | | no | no | | | | | | |
| Any impact to vegetation? | | no | | no | no | | | | | | |
| Any impact to wildlife? | | no | | no | no | | | | | | |