the Of	CONSERVATION

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, November 25, 2024 Time of Arrival: 9am Time of Departure: 1pm

Inspector Name(s): Billy Carnes

Other personnel on site: Randy Broussard [Westlake] Shannon {Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 74* to 81* Partly cloudy SSW 14 mph

Any planned work for today:

Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL- bubbling sites	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
Sulphur Mines Dome				(near BW-22, west						
				side of Central						
ļ	_			Lake)						
R & R Construction working on Levee										
										#1017 160 psi
										tubing 160 psi
										tubing// #1012 70
										psi tubing 70 psi casing// S-7 60 psi
					CL- NO AIR BOAT					tubing 0 psi
					TODAY DIDN'T					casing// S-4 12 psi
		Pad dry - no	Injecting 545 gpm	still bubbling with	INSPECT BUBBLING					tubing 95 psi
		bubbling observed	1416 psi DHG	oil sheen	SITE'S					casing//
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			113 psi				0.85 psi			
Casing Pressure (if applicable)	639 psi		141 psi			275 psi		275 psi	908 psi	
Bubbling?				yes						
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						

