Location: Sulphur Mines Dome Date: Monday, December 2, 2024 Inspector Name(s): Billy Carnes	Time of Arrival:	9:00	INJI	ECTION & MI 617 NORTH	NSERVATION NING DIVISIO 3RD STREET 5E, LA 70802					The second
Other personnel on site: Randy Broussard [Westlake] Vance Hill [Yellowrock] Richard Timpa [Stain's Airboats]										
Weather Conditions (Temp/Wind Speed/Direction, etc.): 48* to 61* Sunny ENE 7 mph Any planned work for today: Check bubbling site's, Cavern Well pressures & some Yellowrock Well pressures										
Any planned work for today: Check bubbling site's, Cavern Well pressures & some Yellowrock Well pressures										
Inspection locations: Sulphur mines dome	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL-bubbling site's	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
R & R Construction working on levee										
		Pad dry - no bubbling observed	Injecting 539 gpm 1416 psi DHG	Still bubbling with oil sheen	CL- 3,4,5,6,17,21,22,24 were still bubbling @ time of inspection all other CL sites were inactive					#1017 190 psi tubing 190 psi casing//#1012 50 psi tubing 50 psi casing// S-7 60 psi tubing 0 psi casing// S-4 14 psi tubing 80 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			109 psi				0.74 psi			
Casing Pressure (if applicable)	637 psi		208 psi			281 psi		275 psi	908 psi	
Bubbling?				yes	yes					
Sheen?				yes	no					
Oil?				yes	no					
Odor?				yes	no					
Any new remedial work?				no	no					
Any impact to vegetation?				no	no					
Any impact to wildlife?				no	no					