INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, December 9, 2024 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM Inspector Name(s): Billy Carnes Other personnel on site: Randy Broussard [Westlake] Vance Hill [Yellowrock] Weather Conditions (Temp/Wind Speed/Direction, etc.): 61* to 68* Cloudy SW 6 mph										
Any planned work for today: Check bubbling sites & some of Westlake Cavern Well pressures & a few of Yellowrock Well pressures										
Inspection locations: Sulphur Mines Dome	Cavern 6X	Cavern Well 7A	Cavern Well 7B	<b>CL-1</b> (near BW-22, west side of Central Lake)	CL bubbling site's	Cavern Well 2	Cavern Well 2a	Vavern Well 4	Cavern Well 20	Yellowrock
R & R Construction working on Levee & drill pad. Protect is working on plugging some old montoring wells.		Fluid on pad witness small bubbling			No Airboat today wasn't able to check other Central lake bubbling site's.					S-4 14 psi tubing 80 psi casing// S-7 55psi tubing 0 psi casing//#1017 100 psi tubing 100 psi casing//#1012 50 psi tubing 50 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			113 psi							
Casing Pressure (if applicable)	636 psi		277 psi			280 psi	0.62 psi	280 psi	918 psi	
Bubbling?		yes		yes						
Sheen?		no		yes						
Oil?		no		yes	ļ					
Odor?		no		yes	ļ					
Any new remedial work?		no		no						
Any impact to vegetation?		no		no						
Any impact to wildlife?		no		no						