NI OF				INSPECTIO	N FORM			1977		
	OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802						al .	BW No. 21	/ No. 10	
							1			BW: No. 20 BW: No. 20
								17788		Attine AN 073566 104 Y 104 (LISN
Office of constrainings										And
Location: Sulphur Mines Dome								BWIND Z		
Date: Tuesday, December 17, 2024	Time of Arrival: 10:00 AM Time of Departure: 1:00 PM								RW, No. 22	
Inspector Name(s): Billy Carnes							16.5	and the subscreen		Stor B. L
	ussard [Westlake] Va	nce Hill [Yellowrok] J	lamie Love [State of L	a] Stan's Airboats op	erator			A CARLES AND	Marcine Marciala RWI.No.2 & 2A	Contraction
Weather Conditions (Temp/Wind Speed/Dire		67* to 77* partly clo	-				No	CA LO	Jose Tor	and a second sec
		stlake & Yellowrock						A A A	BW No. 4	TER CONTRACT
Inspection locations: Sulphur Mines dome	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL bubblings sites	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
R & R Construction working on levee ERM taking air sample's										
		Fluid on pad @ time of inspection	injecting 554 gpm// 1417 psi on DHG	Still bubbling w/oil sheen	CL-3,4,5,6,18,21,24 still bubbling @time of inspection all others were inactive @ time of inspection				Operator flowing/mining well during time of inspection	#1017 60 psi tubing 60 psi casing// #1012 40 psi tubing 40 psi casing//S-7 60 psi tubing 0 psi casing//S-4 12 psi tubing 85 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			117 psi				0.38 psi		206 psi	
Casing Pressure (if applicable)	635 psi		388 psi			287 psi		287 psi	468 psi	
Bubbling?		yes		yes	yes					
Sheen?		no		yes	no					
Oil?		no		yes	no					
Odor?		no		yes	no					
Any new remedial work?		no		no	no					
Any impact to vegetation?		no		no	no					
Any impact to wildlife?		no		no	no					