STATINT OF A	
COT CONSER	Sol a

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location:	Sulphur	Mines Dome
-----------	---------	------------

Date: Monday, January 6, 2025 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: randy Broussard [Westlake] Vance Hill [Yellowrock] Capt. Gavin {Stan's Airboats}

Weather Conditions (Temp/Wind Speed/Direction, etc.): 38 * to 42* Sunny NNW 18 mph [Chilly morning]

Any planned work for today: Check bubbling site's, Cavern Well pressures & some Yellowrock Well pressures/// look @ some containment levee sections.



Inspection locations: Dome	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL bubbling sites	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
R & R Construction working on levee . Lonquest is working on Cavern well 7b to prepare for Sonar work. Also Westlake personal were bleeding pressure/fluid off of Cavern 4 to prepare for Sonar or other cavern work		Fluid on pad observed bubbling	injecting 544 gpm// 1415 psi on dhg [before Well work]	Still bubbling with oil sheen	CL 3,4,5,6,17& 24 were observed bubbling today all others were inactive @ tine of inspection			Operator bleeding pressure/fluid off of Cavern for well work		tubing 140 psi casing// #1012 40 psi tubing 40 psi casing// S-7 65 psi tubing 0 psi casing// S-4 16 psi tubing 385 psi casing { preformed MIPT @ inspectior time]
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			109 psi							
Casing Pressure (if applicable)	626 psi		425 psi			291 psi	0.35 psi		521 psi	
Bubbling?		yes		yes	yes					
Sheen?		no		yes	no					
Oil?		no		yes	no					
Odor?		no		yes	no					
Any new remedial work?		no		no	no					
Any impact to vegetation?		no		no	no					
Any impact to wildlife?		no		no	no					