INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, January 13, 2025 Time of Arrival: 9:00 AM Time of Departure: 12:00 PM Inspector Name(s): Billy Carnes Other personnel on site: Vance Hill [Yellowrock] DeAnn Chapman (Westlake] Weather Conditions (Temp/Wind Speed/Direction, etc.): 51 * to 56 * Partly Cloudy NNE 1mph Any planned work for today: Check Bubbling site's record some of the Cavern Well pressure & check some of Yellowrock Well pressures										
Inspection locations: Sulphur Mines Dome	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west	CL site's	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
				side of Central Lake)						
R & R Construction working on levee and ReCon is surveying R & R work										
		Fluid on pad - bubbling observed	543 gpm injection//1476 psi DHG	still bubbling with an oil sheen	No Airboat Central Lake inspections perform @ this time				Westlake was flowing this well today	#1017 140 psi tubing 140 psi casing// #1012 40 tubing 40 casing// S 7 60 psi tubing 0 psi casing// S-4 15 psi tubing 380 psi casing
Photos taken? (save to F: drive)		_								
Tubing Pressure (if applicable)			106 psi				0.156		114 psi	
Casing Pressure (if applicable)	624 psi		425 psi			297 psi		298 psi	531 psi	
Bubbling?		yes		yes						
Sheen?		no		yes						
Oil?		no		yes						
Odor?		no		yes						
Any new remedial work?		no		no						
Any impact to vegetation?		no		no						
Any impact to wildlife?		no		no						