Location: Sulphur Mines Dome Date: Monday, January 27, 2025 Inspector Name(s): Billy Carnes	Time of Arrival:		INJE DAM	ECTION & MI 617 NORTH BATON ROUC	NSERVATION NING DIVISIO 3RD STREET 5E, LA 70802					
Other personnel on site: DeAnn Chapman [Westlake] Vance Hill [Yellowrock] Collin Todd [Stan's Airboats]										
Weather Conditions (Temp/Wind Speed/Direction, etc.): 51* to 58* light drizzle cloudy N 8 mph Any planned work for today: Inspect bubbling site's, check some Cavern Well pressures & record some of Yellowrock well pressures										
Inspection locations: Sulphur Mines Dome	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL-bubbling site's	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
R & R Construction working on levee & curverts. ERM was getting air samples from bubbling sites		Fluid on pad	injecting 553 gpm//		CL- 3,4,5,6,18,21 & 24// all other CL- sites were inactive @ time of					#1017 40 psi casing 40 psi tubing// #1012 40 psi casing 40 psi tubing// S-7 65psi tubing 0 psi casing// S-4 15 psi tubing 360 psi
		bubbling observed	1417 psi on BHG	oil sheen	inspection					casing
Photos taken? (save to F: drive) Tubing Pressure (if applicable)			104 psi				0.74 psi			
Casing Pressure (if applicable)	620 psi		420 psi			280 psi	0.74 psi	287 psi	415 psi	
Bubbling?	020 por	yes		yes	yes	200 ps.		207 001	120 poi	
Sheen?		no		yes	no					
Oil?		no		yes	no					
Odor?		no		yes	no					
Any new remedial work?		no		no	no					
Any impact to vegetation?		no		no	no					
Any impact to wildlife?		no		no	no					