	INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION							BUT MG 21	N NO 1	
								And An An Strainer		Norman 13 Norman 13 Norman 13 Norman 13 Norman 13 Norman 13 Norman 13 Norman 13
617 NORTH 3RD STREET							1.4			A CAN SN COMPANY
BATON ROUGE, LA 70802										
Location: Sulphur Mines Dome										
Date: Monday, February 10, 2025	Time of Arrival:	9:00	AM	Time of Departure:	1:00	) PM		A CAR AND	RW. No. 22	118-
Inspector Name(s): Billy Carnes							3	Contract States of the		
Other personnel on site: DeAnn Chapman [Westlake] Vance Hill [Yellowrock] Capt. Gavin [Stain's Airboats]										
Weather Conditions (Temp/Wind Speed/Direction, etc.): 51* to 64* Partly cloudy NNE 11 mph										
Any planned work for today: Check bubbling site's, Cavern Well pressure's & some of Yellowrock Well pressure's										
Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL site's	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
Sulphur Mines Dome				(near BW-22, west						
				side of Central	(east side of Central					
				Lake)	Lake)					
R & R Construction is working on the containment levee										
										#1017 40 psi tubing 40 psi casing//
										#1012 250 psi
					CL- 3,4,5,6,21 & 24					tubing 250 psi
					were actively					casing// S-7 70 psi
			551 GPM		bubbling all other					tubing 0 psi
		Pad dry no bubbling	injecting// 1468 pi		CL site's were					casing// S-4 14 psi tubing 350 psi
			gauge	Still bubbling with a oil sheen	inactive @ time of inspection					casing
Photos taken? (save to F: drive)			88-							
Tubing Pressure (if applicable)			101 psi							
Casing Pressure (if applicable)	618 psi		416 psi			280 psi	0.82 psi	284 psi	474 psi	
Bubbling?	010 p3		410 p31	ves	ves	200 p31	0.02 p31	204 051	474 p31	
Sheen?				yes	no					
Oil?				yes	no					
Odor?				yes	no					
Any new remedial work?				no	no					
Any impact to vegetation?				no	no					
Any impact to wildlife?				no	no					