INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, February 17, 2025 Time of Arrival: 0930 am Time of Departure: 1200 pm Inspector Name(s): Billy Carnes Other personnel on site: DeAnn Chapman [Westlake] Vance Hill [Yellowrock] Weather Conditions (Temp/Wind Speed/Direction, etc.): 43* to 51* Sunny ENE 9 mph Any planned work for today: Check Cavern Well pressures, look at some of Yellowrock Well pressures & check on Containment Levee being built										
Inspection locations: Sulphur Mines Dome	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Central Lake	Yellowrock
R & R Construction working on Containment Levee & ERM is sampling water wells, water & bubbling site's		Fluid on pad bubbling observed	operator injecting 560 gpm 1479 psi on DHG	Still bubbling with oil sheen			Operator was flowing Well @ time of inspection		No inspections done today [no Airboat]	#1017 250 psi tubing 250 psi casing// #1012 %0 psi tubing 50 psi casing// S-7 70 psi tubing 0 psi casing// S-4 15 psi tubing 330 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			108 psi			0.70 psi				
Casing Pressure (if applicable)	617 psi		419 psi		281 psi		355 psi	498 psi		
Bubbling?		yes		yes						
Sheen?		no		yes						
Oil?		no		yes						
Odor?		no		yes						
Any new remedial work?		no		no						
Any impact to vegetation?		no		no						
Any impact to wildlife?		no		no						