INSPECTION FORM   OFFICE OF CONSERVATION   INSPECTION & MINING DIVISION   Inspector   Inspector   Inspector   Inspector Name(s):   Billy Carnes:   Inspector Name(s):   Inspector Name(s):   Billy Carnes:   Inspector Name(s):   Billy Carnes:   Inspector Name(s):   Billy Carnes:   Inspector Name(s):   Billy Carnes:   Inspector Name(s): </th										
Inspection locations: Sulphur mines dome	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL site's	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
R & R Construction was tying to work on containment levee but dirt is wet from the rain this weelend		fluid on pad bubbling observed	injecting 564 gpm//down hole gauge 1478 psi	Still bubbling with oil sheen	CL- 3,4,5,6,17,22 & 24 were active andall other bubbling site's were inactive during inspection					#1017 150 psi tubing 150 psi casing// #1012 40 psi tubing 40 psi casing// S-7 15 psi tubing 330 psi casing// S-4 0 psi tubing 70 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			106 psi							
Casing Pressure (if applicable)	617 psi		416 psi			279 psi	0.39 psi	281 psi	519 psi	
Bubbling?		yes		yes	yes					
Sheen?		no		yes	no					
Oil?		no		yes	no					
Odor?		no		yes	no					
Any new remedial work?		no		no	no					
Any impact to vegetation?		no		no	no					
Any impact to wildlife?		no		no	no					