

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, March 3, 2025 Time of Arrival: 9:20 AM Time of Departure: 1:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: DeAnn Chapman [Westlake] Vance Hill [Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 66* to 73* Cloudy misty rain ESE 10 mph

Any planned work for today: Check Cavern Well Pressure's, some Yellowrock Well pressure's and the progress of the containment levee being built



Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	Central Lake	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
Sulphur Mines Dome				(near BW-22, west						
				side of Central						
				Lake)						
R & R Construction is working on										
containment levee and Drill pad. Westlake										
is bleeding pressure off of Cavern Well										
#004 during time of inspection										#1017 250 psi 250
										tubing 250 psi
										casing//#1012 40
					No Inspections of					psi tubing 40 psi// S 7 15 psi tubing 330
					the bubbling site's					psi casing// S-4 70
		Fluid on Pad today	571 gpm injecting	Still bubbling w/oil	in Central Lake					psi tubing 0 psi
				sheen	today					casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			116 psi				0.23 psi	234 psi		
Casing Pressure (if applicable)	616 psi		417 psi			283 psi			485 psi	
Bubbling?		yes		yes						
Sheen?		no		yes						
Oil?		no		yes						
Odor?		no		yes						
Any new remedial work?		no		no						
Any impact to vegetation?		no		no						
Any impact to wildlife?		no		no						