

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, March 10, 2025 Time of Arrival: 9:15 AM Time of Departure: 1:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: Kevin LaVergne [Westlake] Vance Hill [Yellowrock] Capt. Gavin [Stan's Airboats]
Weather Conditions (Temp/Wind Speed/Direction, etc.): 50* to 65* Clear Sunny little windy NNW 10 mph

Any planned work for today: Check bubbling site's, Cavern Well pressure's, Some Yellowrock Well pressure's and check on the Containment Levee work



Inspection locations: Sulphur Mines Dome	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL Site's	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
R & R Construction working on containment Levee & Well Pad		Fluid on Pad bubbling observed	Injecting 567 gpm Down Hole Gauge 1471 psi	still bubbling w/oil sheen	CL Bubbling site's 3,4,5,6,17,21 & 24 active @ time of inspection all other CL site's were inactive @ time of inspection					#1017 245 psi tubing 245 psi casing// #1012 60 psi tubing 60 psi casing// S-7 70 psi tubing 0 psi casing// S-4 15 psi tubing 320 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			117 psi				0.50 psi			
Casing Pressure (if applicable)	615 psi		419 psi			284 psi		285 psi	509 psi	
Bubbling?		yes		yes	yes					
Sheen?		no		yes	no					
Oil?		no		yes	no					
Odor?		no		yes	no					
Any new remedial work?		no		no	no					
Any impact to vegetation?		no		no	no					
Any impact to wildlife?		no		no	no					