	INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802									A series of the
Location: Sulphur Mines Dome	The state of the s	0.00		T		0.014			PEG PROPERTY	
Date: Monday, March 17, 2025 Inspector Name(s): Billy Carnes	Time of Arrival:	9:00) AM	Time of Departure	: 12:0	00 PM		Production of the second		
•	napman [westlake] Va	nce Hill]Yellowrock]						And the	Hantlin Verzak (2A) RW, No. z & zA	
Weather Conditions (Temp/Wind Speed/Direction, etc.): 53* to 70* ENE 1 mph										
Any planned work for today: Check Bubbling site's, Cavern Well pressure's & some of the Yellowrock Well pressure										
Inspection locations: Sulphur Mines Dome	Cavern 6X	Cavern Well 7A		CL-1 (near BW-22, west side of Central Lake)	CL site's	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
R & R Construction is working on the containment levee		Pad dry no bubbling observed	579 gpm // DWG 1469 psi	Still bubbling with oil sheen	No Boat today - no observations of any Central Lake bubbles					#1017 250 psi tubing 250 psi tubing// #1012 40 psi tubing 40 psi casing// 5-7 70 psi tubing 0 psi casing// 15 psi tubing 305 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			103 psi							
Casing Pressure (if applicable)	615 psi		417 psi			283 psi	0.42 psi	282 psi	530 psi	
Bubbling?				yes						
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						
					1					