

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, March 24, 2025 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: DeAnn Chapman [Westlake] Vance Hill [Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 65* to 76* Partly cloudy ENE 4 mph

Any planned work for today: Check bubbling site's, Cavern Well pressure's & some of Yellowrock Well pressure's



Inspection locations: Sulphur Mines Dome	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	CL site's	Yellowrock
R & R Construction is working on containment levee & drill pad										
		Fluid on pad bubbling observed	Injecting 571 gpm 1468 psi on down hole gauge	Bubbling with Oil sheen					CL 3,4,5,6,17,18 & 24 site's still bubblin all others site's were inactived during inspection	#1017 30 psi tubing 30 psi casing// #1012 40 psi tubing 40 psi casing// S-7 70 psi tubing 0 psi casing// S-4 15 psi tubing 300 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			106 psi			0.03 psi				
Casing Pressure (if applicable)	614 psi		417 psi		280 psi		289 psi	514 psi		
Bubbling?		yes		yes						
Sheen?		no		yes						
Oil?		no		yes						
Odor?		no		yes						
Any new remedial work?		no		no						
Any impact to vegetation?		no		no						
Any impact to wildlife?		no		no						