

## INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Tuesday, April 8, 2025 Time of Arrival: 9:30 AM Time of Departure: 1:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: DeAnn Chapman [Westlake] Vance Hill [Yellowrock]
Weather Conditions (Temp/Wind Speed/Direction, etc.): 67\* to 69\* Sunny N 5 mph

Any planned work for today: Check work on drill pad - containment levee, Cavern Well pressure's & some of Yellowrock well pressure's



Inspection locations: Sulphur Mines Dome	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL site's	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
R & R Construction is working on Drill pad & Containment levee		Fluid on pad bubbling observed		Still bubbling with oil sheen	CL site's still bubbling 3.4.5.6,18,22 & 24. All other CL site's were inactive @ time of inspection					#1017 250 psi tubing 250 psi casing// #1912 40 psi tubing 40 psi casing// S-7 70 psi tubing 0 psi casing// S-4 15 psi tubing 290 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			110 psi							
Casing Pressure (if applicable)	614 psi		426 psi			282 psi	0.23 psi	282 psi	391 psi	
Bubbling?		yes		yes	yes					
Sheen?		no		yes	no					
Oil?		no		yes	no					
Odor?		no		yes	no					
Any new remedial work?		no		no	no					
Any impact to vegetation?		no		no	no					
Any impact to wildlife?		no		no	no					