

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, April 14, 2025 Time of Arrival: 9:00 AM Time of Departure: 12:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: Josh Bradley [Westlake] Vance Hill [Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 76* to 78* Partly cloudy SSW 15 mph

Any planned work for today: Check bubbling site's, Cavern Well pressure's & some of Yellowrock well pressure's



Inspection locations: Sulphur Mines Dome	Cavern 6X	Cavern Well 7A		CL-1 (near BW-22, west side of Central Lake)	CL site's	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
R & R construction working on drill pad & containment levee		Pad dry no bubbling observed			No boat ride into Central Lake today during inspection					#1017 250 psi tubing 250 psi casing// #1012 40 psi tubing 40 psi casing// S-7 70 psi tubing 0 psi casing// S-4 15 psi tubing 280 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			109 psi							
Casing Pressure (if applicable)	614 psi		422 psi			280 psi	0.27 psi	282 psi	391 psi	
Bubbling?				yes						
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						