

## INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, April 21, 2025 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: Randy Broussard [Westlake] Vance Hill [Yellowrock] Capt. Richard [Stan's Airboat's]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 77\* to 78\* Partly Cloudy SSE 8 mph

Any planned work for today: Check bubbling site's, Cavern Well pressure's & Some of Yellowrock Well Pressure's



Inspection locations: Sulphur Mines Salt Dome	Cavern 6X	Cavern Well 7A		CL-1 (near BW-22, west	CL- sites	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
			l	side of Central Lake)						
R & R Construction working on containment & drill pad. Loniquist working Cavern Well 7b Sonar & other Wireline work. (see their report)		Pad dry No			CL-3,4,5,6,18,21,22 & 24 observed bubbling during inspection all oring were inactive during inspection					#1017 250 psi tubing 250 psi casing//#1012 40 psi tubing 40 psi casing// S-7 70 psi tubing 0 psi casing//S-4 15 psi tubing 280 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			111 psi							
Casing Pressure (if applicable)	614 psi		420 psi			286 psi	0.23 psi	289 psi	453 psi	
Bubbling?				yes	yes					
Sheen?				yes	no					
Oil?				yes	no					
Odor?				yes	no					
Any new remedial work?				no	no					
Any impact to vegetation?				no	no					
Any impact to wildlife?				no	no					