INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, April 28, 2025 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM Inspector Name(s): Billy Carnes Other personnel on site: Josh Bradley [Westlake] Vance Hill [Yellowrock] Weather Conditions (Temp/Wind Speed/Direction, etc.): 80* to 84* Sunny SSE 11 mph Any planned work for today: Check some bubbling site's, Cavern well pressures dome of Yellowrock Well pressures										
Inspection locations: Sulphur Mines Dome	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20		Yellowrock
R & R working on containment levee & Well drill pad		Fluid on pad bubbling observed	Injecting 568 gpm // 1469 psi down hole gauge	Still bubbling with oil sheen						#1017 250 psi tubing 250 psi casing// #1012 40 psi tubing 40 psi casing//S-7 70 psi tubing o psi casing// S-4 15 psi tubing 270 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			108 psi							
Casing Pressure (if applicable)	613 psi		418 psi		292 psi	0	296 psi	479 psi		
Bubbling?		yes		yes						
Sheen?		no		yes						
Oil?		no		yes						
Odor?		no		yes						
Any new remedial work?		no		no						
Any impact to vegetation?		no		no						
Any impact to wildlife?		no		no						