Location: Sulphur Mines Dome Date: Monday, May 19, 2025 Inspector Name(s): Billy Carnes	Time of Arrival:	9:0	INJ	INSPECTIO OFFICE OF CO ECTION & MI 617 NORTH BATON ROUC	NSERVATIO INING DIVISI 3RD STREET GE, LA 70802	ION T				E CERTION A CERTION
Other personnel on site: Randy Broussard [Westlake] Vance Hill [Yellowrock]										
Weather Conditions (Temp/Wind Speed/Direction, etc.): 81* to 85* Partly cloudy SSE 16 mph										
Any planned work for today: Inspect some bubbling sites, Check some Cavern Well pressures and some Yellowrock Well pressures										
Inspection locations: Sulphur Mines Dome	Cavern 6X	Cavern Well 7A	Cavern Well 7B	<b>CL-1</b> (near BW-22, west side of Central Lake)	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20		Yellpwrock
R & R Construction working on containment levee		No fluid on pad during inapection NO bubbling observed	Injecting 589 gpm // 1468 psi on the down hole gauge	Still bubbling with a Oil sheen						#1017 250 psi tubing 250 psi casing// #1012 40 psi tubing 40 psi casing// S-7 70 psi tubing 0 psi casing// S-4 15 psi tubing 260 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			109 psi							
Casing Pressure (if applicable)	613 psi		417 psi		305 psi	0.313 psi	304 psi	474 psi		
Bubbling?				yes						
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						