INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, June 2, 2025 Time of Arrival: 8:00 AM Time of Departure: 1:00 PM Inspector Name(s): Billy Carnes Dther personnel on site: Vance Hill [Yellowrock] Josh Bradley [Westlake] Weather Conditions (Temp/Wind Speed/Direction, etc.): 82* to 85* Sunny ESE 4 mph Any planned work for today: Check Bubbling site's, Cavern Well Pressure's & some of Yellowrock Well pressure's										
Inspection locations: Sulphur Mines Dome	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20		Yellowrock
R & R Construction working on containment levee		Fluid on pad	Injecting 584 gpm 1467 psi on Down hole gauge	Lake) Still bubbling with Oil sheen	Operator is getting Cavern really for workover					#1017 250 psi tubing 250 psi casing// #1012 40 psi tubing 40 psi casing// S-7 70 psi tubing 0 psi casing// S-4 15 psi tubing 250 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			109 psi							
Casing Pressure (if applicable)	612 psi		416 psi			0.35 psi	302 psi	462 psi		
Bubbling?		yes		yes						
Sheen?		no		yes						
Oil?		no		yes						
Odor?		no		yes						
Any new remedial work?		no		no						
Any impact to vegetation?		no		no						
Any impact to wildlife?		no		no						