

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Tuesday, June 16, 2015 Time of Arrival: 9:30 AM Time of Departure: 1:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: Josh Bradley [Westlake] Vance Hill {Yellowrock}

Weather Conditions (Temp/Wind Speed/Direction, etc.): 79* to 77* Partly Cloudy/Rainy SSE 7mph

Any planned work for today: Check Bubbling site's, Cavern Well pressure's & some of Yellowrock Well pressure's



Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
Sulphur Mines Dome				(near BW-22, west					
				side of Central					
	.			Lake)					
R & R Construction was shut down due to weather									#1017 230 psi tubing 230 psi
									casing// #1012 40 psi tubing 40 psi ps casing// S-7 70 psi tubing 0 psi
			Injecting 553 gpm		Lonquist has Well				casing// S-4 15 psi
		Fluid on pad	Down hole gauge	Still bubbling with	still down, gauges				tubing 245 psi
		Bubbling observed	reading 1473 psi	an Oil sheen	are not hookup yet				casing
Photos taken? (save to F: drive)									
Tubing Pressure (if applicable)			109 psi						
Casing Pressure (if applicable)	613 psi		425 psi			0.82 psi	304 psi	430 psi	
Bubbling?		yes		yes					
Sheen?		no		yes					
Oil?		no		yes					
Odor?		no		yes					
Any new remedial work?		no		no					
Any impact to vegetation?		no		no					
Any impact to wildlife?		no		no					