Location: Sulphur Mines Dome Date: Monday, June 23, 2025 Inspector Name(s): Billy Carnes Other personnel on site: Randy Brou Weather Conditions (Temp/Wind Speed/Dire	une 23, 2025 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM r Carnes Randy Broussard [Westlake] Vance Hill [Yellowrock]									
Any planned work for today: Check bubbling sites, Cavern Well pressures & check some of Yellowrock well pressures										
Inspection locations: Sulphur Mines Dome	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20		Yellowrock
R & R Construction working on containment levee and Shea-Bros working on drill holes for the base of the drilling rig. Tiberius is working on Cavern Well #022 for Sonar & other Cavern Work.		Pad dry no bubbling observed	Injecting 546 gpm 1474 psi on downhole gauge	Still bubbling with oil sheen	Gauges and electronic monitoring has not been installed back on Well.					#1017 230 psi tubing 230 psi casing// #1012 40 psi tubing 40 psi casing// S-7 70 psi tubing 0 psi casing// S-4 15 psi tubing 240 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			107 psi							
Casing Pressure (if applicable)	614 psi		426 psi			0.89 psi	306 psi	461 psi		
Bubbling?				yes						
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						