

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, June 30, 2025 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: DeAnn Chapman [Westlake] Vance Hill [yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 88* to 91* Sunny 1st then partly cloudy HOT/HUMID SSW 4 mph

Any planned work for today: Check bubbling Site's, Cavern Well pressure's & some of Yellowrock Well pressure's, also the progress of the building of the containment levee

Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
Sulphur Mines Salt Dome				(near BW-22, west					
				side of Central					
				Lake)					
R & R Construction working on Containment Levee. Morris-Shea Bridge construction working on drilled bore holes									#1017 30 psi tubing
for Drilling Rig base.									30 psi casing//
									#1012 40 psi tubing 40 psi casing// S-7
									20 psi tubing 0 psi
			Injecting 540 gpm						casing// S-4 16 psi
		Fluid on pad	// 1474 psi on	Still bubbling with					tubing 240 psi
		bubbling observed	downhole gauge	Oil sheen					casing
Photos taken? (save to F: drive)									
Tubing Pressure (if applicable)			109 psi						
Casing Pressure (if applicable)	614 psi		426 psi		304 psi	1.60 psi	285 psi	438 psi	
Bubbling?		yes		yes					
Sheen?		no		yes					
Oil?		no		yes					
Odor?		no		yes					
Any new remedial work?		no		no					
Any impact to vegetation?		no		no					
Any impact to wildlife?		no		no					