

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, July 7, 2025 9:00 AM Time of Departure: 4:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: DeAnn Chapman [Westlake] Vance Hill [Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 86* to 91* Sunny/Partly Cloudy Hot .. SSW 4 mph

Any planned work for today: Check bubbling site's, pressure's on some Cavern Wells and some of Yellowrock Well pressures



Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
Sulphur Mines Dome				(near BW-22, west					
				side of Central					
				Lake)					
D O D Country attenues and the second									
R & R Construction working on containment Levee. Tiberius has contract									
crew putting Cavern Well #018 back									
together.									#1017 30 psi tubing
together.									30 psi casing//
			L						#1012 40 psi tubing
			Injecting 534 gpm & downhole gauge						40 psi casing// S-7 70 psi tubing 0 psi
		Pad had fluid on	has 1474 psi on						casing// S-4 15 psi
		surface bubbling		Still bubbling with					tubing 235 psi
		observed	control room.	oil sheen					casing
Photos taken? (save to F: drive)									
Tubing Pressure (if applicable)			107 psi			2,07 psi			
Casing Pressure (if applicable)	615 psi		426 psi		293 psi		295 psi	418 psi	
Bubbling?		yes		yes					
Sheen?		no		yes					
Oil?		no		yes					
Odor?		no		yes					
Any new remedial work?		no		no					
Any impact to vegetation?		no		no					
Any impact to wildlife?		no		no					