

## INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, July 14, 2025 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: DeAnn Chapman [Westlak] Vance Hill [Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 88\* to 89\* Partly Cloudy SSW 3 mph

Any planned work for today: Check bubbling sites, Cavern Well pressures & some of Yellowrock Well pressure's



Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
Sulphur Mines Dome				(near BW-22, west					
				side of Central					
			1	Lake)					
R & R Construction still working on cintainment levee		Fluid on pad		Still bubbling with					#1017 120 psi tubing 120 psi casing// #1012 40 psi tubing 40 psi casing// S-7 70 psi tubing 0 psi casing// S-4 16 psi tubing 230 psi
		bubbling observed	Hole Gauge	Oil sheen					casing
Photos taken? (save to F: drive)									
Tubing Pressure (if applicable)			106 psi						
Casing Pressure (if applicable)	616 psi		425 psi		285 psi	2,11 psi	286 psi	492 psi	
Bubbling?		yes		yes					
Sheen?		no		yes					
Oil?		no		yes					
Odor?		no		yes					
Any new remedial work?		no		no					
Any impact to vegetation?		no		no					
Any impact to wildlife?		no		no					