

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, July 21, 2025 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: DeAnn Chapman [Westlake] Shannon {Yellowrock] Chad Trahan [Stan's Airboats]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 88* to 92* Partly Cloudy HOT SSW 6 mph

Any planned work for today: Check bubbling site's, Cavern Well Pressure's, R & R Construction work and some of Yellowrock Well pressure's



Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL-Sites	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
Sulphur Mines Salt Dome				(near BW-22, west						
				side of Central						
	4			Lake)						1
R & R Construction working on										
containment levee. ERM is taking air &					CL 2 F C 4 7 4 0 0 2 4					
water samples.					CL-3,5,6,17,18 & 24					#1017 (0: +
					were bubbling today during					#1017 60 psi tubing 60 psi casing//
					Inspection all othe					#1012 40 psi tubing
					CL sites were					40 psi casing// S-7
					inactive during					70 psi tubing 0 psi
			Injecting 528 gpm/		inspection. CL-4					casing// S-4 16 psi
		Pad dry no bubbling		Still bubbling w/oil	pipe marking site is					tubing 230 psi
		observed	Downhole gauge	sheen	missing.					casing
Photos taken? (save to F: drive)										, and the second
Tubing Pressure (if applicable)			100 psi							
Casing Pressure (if applicable)	290 psi		419 psi			290 psi	2.11 psi	292 psi	412 psi	
Bubbling?				yes	yes					
Sheen?				yes	no					
Oil?				yes	no					
Odor?				yes	no					
Any new remedial work?				no	no					
Any impact to vegetation?				no	no					
Any impact to wildlife?				no	no					