

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, July 28, 2025 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: DeAnn Chapman [Westlake] Vance Hill [Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 88* to 90* Partly Cloudy WNW 2 mph

Any planned work for today: Check Bubbling site's Cavern Well pressures & some of Yellowrock Well pressure's



Inspection locations: Sulphur Mines Saltdome	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
R & R Construction working on containment levee		Pad dry no bubbling observed	Injecting 519 gpm 3 Downhole gauge 1470 psi	Still bubbling with Oil sheen					#1017 120 psi tubing 120 psi Casing// #1012 40 psi tubing 40 psi casing// S-7 70 psi tubing 0 psi casing// S-4 16 psi tubing 225 psi casing
Photos taken? (save to F: drive)									
Tubing Pressure (if applicable)			101 psi						
Casing Pressure (if applicable)	616 psi		421 psi		295 psi	1.76 psi	297 psi	446 psi	
Bubbling?				yes					
Sheen?				yes					
Oil?				yes					
Odor?				yes					
Any new remedial work?				no					
Any impact to vegetation?				no					
Any impact to wildlife?				no					