

## INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Wednesday, August 6, 2025 Time of Arrival: 9:30 AM Time of Departure: 12:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: DeAnn Chapman [Westlake] Vance Hill [Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 82\* to 89\* Partly cloudy 3 mph SE

Any planned work for today: Check bubbling site's, check Cavern Well pressure's and check on some Yellowrock Well pressure's



Inspection locations:	Cavern 6X	Cavern Well 7A			Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20		Yellowrock
Sulphur Mines Dome				(near BW-22, west						
				side of Central						
				Lake)		ļ				
Pelican Land Surveyors working in Salt lake										
& Central lake checking water depths										
a central take diceking water depuis										#1017 120 psi
										tubing 120 psi casing// #1012 40
										psi tubing 40 psi
										casing// S-7 70 psi
			injecting 519 gpm//							tubing 0 psi
			Down hole pressure							casing// S-4 16 psi
		Pad dry no bubbling	gauge reading 1470	Still bubbling with						tubing 220 psi
		observed	psi	Oil sheen						casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			98 psi							
Casing Pressure (if applicable)	614		419 psi		287 psi	0.93	297 psi	479 psi		
Bubbling?				yes						
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						
									1	