

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, August 11, 2025 Time of Arrival: 9:30 AM Time of Departure: 1:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: DeAnn Chapman [Westlake] Vance Hill [Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 79* to 90* cloudy/misty rain ended early ENE 5 mph

Any planned work for today: Check bubbling site's, Cavern Well pressure's and some of Yellowrock Well pressure's



Inspection locations: Sulphur Mines Dome	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
No extra work today		Pad dry no bubbling observed	Injecting 524 psi g gpm// 1470 psi on down hole gauge	Still bubbling with Oil sheen					#1017 20 psi tubing 20 psi casing// #1012 40 psi tubing 40 psi casing// 70 psi tubing 0 psi casing// 16 psi tubing 220 psi casing. Vance Hill flowed # 1017 this weekend
Photos taken? (save to F: drive)									
Tubing Pressure (if applicable)			102 psi						
Casing Pressure (if applicable)	614 psi		420 psi		287 psi	0.85 psi	287 psi	496 psi	
Bubbling?				yes					
Sheen?				yes					
Oil?				yes					
Odor?				yes					
Any new remedial work?				no					
Any impact to vegetation?				no					
Any impact to wildlife?				no					