

## INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, August 18, 2025 Time of Arrival: 8:30 AM Time of Departure: 12:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: Kevin LaVergne [Westlake] Vance Hill [Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 83\* to 93\* {hot & humid} N 6 mph partly cloudy

Any planned work for today: Check bubbling site's, Cavern Well pressures & some of Yellowrock Well pressure's



Inspection locations: Sulphur Mines Salt Dome	Cavern 6X	Cavern Well 7A		CL-1 (near BW-22, west side of Central Lake)	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
R & R Construction working on comtainment levee.		Pad dry no bubbling observed	; injecting 517 gpm// BHG 1470 psi	Still bubbling with oil sheen					#1017 180 psi tubing 180 psi casing// #1012 40 psi tubing 40 psi casing// 5-7 70 psi tubing 0 psi casing// 5-4 15 psi tubing 220 psi casing
Photos taken? (save to F: drive)									
Tubing Pressure (if applicable)			98 psi			1.0 psi			
Casing Pressure (if applicable)	613 psi		419 psi		273 psi		274 psi	487 psi	
Bubbling?				yes					
Sheen?				yes					
Oil?				yes					
Odor?				yes					
Any new remedial work?				no					
Any impact to vegetation?				no					
Any impact to wildlife?				no					