

NARRATIVE REPORT

DNR/Office of Conservation
Operations Division

Serial Number	Date 01/27/23	Operator West Lake Chemical ()
Lease Name	Address	
Location (Sec, Twp, Rng / Parish) Calcasieu Parish		
Field Sulphur Mines ()	Phone ()	-
DNR / CES - Keith Goutreaux	Contact Josh Lradley	

R E M A R K S

08:00 AM - 09:39 AM - Travel to Sulphur Mine Field / 43 degrees / Cloudy / SSE Wind 6mph

Inspection Per Mining & Injection request

Yellow Rock (6-land locations on West side of dome)

#209459 - Fee 1012 / 125 psi Tbg / 125 psi Csg

#210185 - Fee 1017 / 105 psi Tbg / 105 psi Csg

#209445 - Fee 1013 / SHUT IN

#159213 - Fee 942 / 100 psi Tbg / Csg shut in, No gauge

#189416 - Fee 969 / Tbg shut in / 70 psi Csg

#207343 - Fee 1007 / SHUT IN

WESTLAKE CHEMICAL

01/27/2023 - 09:50 AM / sign in - 11:05 AM / sign out /

Near LGS #1 P&A site, SE corner of Interior pond / GPS - NAD 83 (N30-15'-12.3" / W93-24'-33.3")

Airboat operations from 01/26/23 knocked down vegetation for more visibility

No visible bubbling from land / No visible sheen / No visible sign of Impact to wildlife or vegetation

Remedial dirt work performed to better seal off holding pit near LGS #1 P&A wellcap

Injection fluid moved from 7B to #20 well Injection (land location)

542 psi / 4.1 BPM

Cavern 6X (land location)

200 psi Tbg / 180 psi Csg

Cavern 7B (land location)

86.2 psi Tbg / 438.5 psi Csg

Cavern 7A P&A well (land location)

Bubbling same as last visit / no visible sheen or product

Behind Cavern #22 / Westside of Interior pond (pit dug to contain oil sheen)

Bubbling still present / GPS - NAD 83 (N30-15'-11.2" / W93-24'-48.0")

Sheen being contained, no visible contamination outside of pit

Remedial work to deepen containment performed with added booming material to catch any seepage

11:05 AM resume normal duties

1/27/23 - CES - Keith Goutreaux