

NARRATIVE REPORT

DNR/Office of Conservation  
Operations Division

Serial Number	Date 02/10/23	Operator West Lake Chemical ( )
Lease Name	Address	
Location (Sec, Twp, Rng / Parish) Calcasieu Parish		
Field Sulphur Mines ( )	Phone ( ) -	
DNR / CES - Keith Goutreaux	Contact Josh Bradley	

R E M A R K S

9:00 am to 10:30 am / Travel to Sulphur Mine field for M&I field inspection on leaking cavern

10:35 am sign in - 1:00 pm sign out / 60 degrees - Cloudy sky - N.N.W. @ 6 mph

Yellow Rock ( 6-land locations on West side of dome)

#209459 - Fee 1012 / 50 psi Tbg / 50 psi Csg

#210185 - Fee 1017 / 200 psi Tbg / 135 psi Csg

#209445 - Fee 1013 / 0 psi Tbg / 30 psi Csg

#159213 - Fee 942 / 75 psi Tbg / 105 psi Csg

#189416 - Fee 969 / 84 psi Tbg / 70 psi Csg

#207343 - Fee 1007 / SHUT IN

WESTLAKE CHEMICAL

2/10/2023 - New Requirements, Sign In - sign for Work Permit, FRC's, H2S Monitor, Safety Glasses, Steel Toes and fill in work activity performed to be returned and signed once activity is completed upon sign-out.

Near LGS #1 P&A site, SE corner of Interior pond / GPS - NAD 83 ( N30-15'-12.3" / W93-24'-33.3" )

No visible bubbling from land / No visible sheen / No visible sign of Impact to wildlife of vegetation

Injection on #20 Oil pad Shut Down

Cavern 6X (land location)

200 psi Tbg / 185 psi Csg

"Locked Gate" Cavern 7B Injection (land location)

90 psi Tbg / 448 psi Csg / 248 gal/min

"Locked Gate" Cavern 7A P&A well (land location)

Bubbling same as last visit / no visible sheen or product

Behind Cavern #22 / Westside of Interior pond (pit dug to contain oil sheen)

Bubbling still present / GPS - NAD 83 (N30-15'-11.2" / W93-24'-48.0")

Sheen being contained, no visible contamination outside of pit, added more absorbent boom to contain due to rainy weather

1:00 PM resume normal duties

CES - Keith Goutreaux  
2/10/23

Original / Baton Rouge, Yellow / Operator, PINK / Inspector